

JOHN H. GIBBONS
DIRECTOR
DANIEL DE SIMONE
DEPUTY DIRECTOR

Congress of the United States
OFFICE OF TECHNOLOGY ASSESSMENT
WASHINGTON, D.C. 20510

5/25/80

ERRATA - AN ASSESSMENT OF OIL SHALE TECHNOLOGIES

1. The shading on Figure 2, page 7 is incorrect:
SEE INSTEAD FIGURE 13, PAGE 90.
2. Issue 4, p. 32: The total estimated cost of
pollution control should be **2.4 to 6.0** cents/gal.
3. Figure 51, p. 187: The minimum and maximum
increases from environmental costs should fall
lower on the graph (about 2 x 1971 estimate).
4. Page 60, Table 8, Site 11/line 11, under status
should read: Initial environmental, health
and safety tests underway.
5. Page 136, first column, lines 6 and 7, should
read: Multi Mineral has begun use of an
8-ft-diameter shaft. . . .